

MS-012 Richard G. Snyder Papers

Drawer 10 NTSB Reports / UK Accidents 1974-76 / Transport Canada 1977

Drawer	File	Title	Dates
10 (1of 2)	1	National Transportation Safety Board (NTSB) "Loss of Control on Takeoff Cleveland-Hopkins International Airport Cleveland, Ohio"	1991
10 (1of 2)	2	National Transportation Safety Board (NTSB) "Takeoff Stall in Icing Condition"	1992
10 (1of 2)	3	National Transportation Safety Board (NTSB) "Controlled Flight into Terrain Unalakleet, Alaska"	1990
10 (1of 2)	4	National Transportation Safety Board (NTSB) "Airline Passenger Safety Education: A Review of Methods Used To Present Safety Information"	1985
10 (1of 2)	5	National Transportation Safety Board (NTSB) "Aircraft Accident /Incident Summary Report; Beechjet, N25BR"	1991
10 (1of 2)	6	National Transportation Safety Board (NTSB) "Aircraft Accident Report; Metro III, SA227 AC; Cary, North Carolina"	1988
10 (1of 2)	7	National Transportation Safety Board (NTSB) "United Airlines Flight 585 Boeing 737-291, N999UA Uncontrolled Collision with Terrain for Underestimated Reasons 4 miles South of Colorado Springs Airport"	1991
10 (1of 2)	8	National Transportation Safety Board (NTSB) "In-Flight Structural Breakup; Eagle Lake, Texas"	1991
10 (1of 2)	9	National Transportation Safety Board (NTSB) "In-Flight Collision with Terrain Mount Haleakalala, Maui, Hawaii"	1992
10 (1of 2)	10	National Transportation Safety Board (NTSB) "In-Flight Loss of Propeller Blade and Uncontrolled Collision with Terrain; Zwingle, Iowa"	1993
10 (1of 2)	11	National Transportation Safety Board (NTSB) "Controlled Flight into Terrain; Shelton, Nebraska"	1994
10 (1of 2)	12	National Transportation Safety Board (NTSB) "Runway Departure Following Landing; DC-10-30, Dallas, Texas"	1993
10 (1of 2)	13	National Transportation Safety Board (NTSB) "Inadvertent In-Flight Slat Deployment; China Eastern Airline Flight 583"	1993
10 (1of 2)	14	National Transportation Safety Board (NTSB) "In-Flight Turbulence Encounter and Loss of the Elevators; China Airlines Flight CI-012; Japan"	1992
10 (1of 2)	15	National Transportation Safety Board (NTSB) "In-Flight Loss of Control, Leading to Forced Landing and Runway Overrun; Continental Express, INC., N24706; Pine Bluff, Arkansas"	1993

10 (1of 2)	16	National Transportation Safety Board (NTSB) "Runway Departure Following Landing American Airlines Flight 102, McDonnell Douglas DC-10-30, Dallas, Texas"	1993
10 (1of 2)	17	National Transportation Safety Board (NTSB) "Aircraft Accident / Incident Summary Report"	1987
10 (1of 2)	18	Civil Aviation Authority "Accident to Aircraft on the British Register"	1974
10 (1of 2)	19	Civil Aviation Authority "Accident to Aircraft on the British Register"	1975
10 (1of 2)	20	Civil Aviation Authority "Accident to Aircraft on the British Register"	1976
10 (1of 2)	21	Civil Aviation Authority "Accident to Aircraft on the British Register"	1977
10 (1of 2)	22	Civil Aviation Authority "Accident to Aircraft on the British Register"	1973
10 (1of 2)	23	Civil Aviation Authority "Accident to Aircraft on the British Register"	1979
10 (1of 2)	24	Civil Aviation Authority "Accident to Aircraft on the British Register"	1978
10 (1of 2)	25	National Transportation Safety Board (NTSB) "Air Transport International, INC., Flight 805; Douglas DC-8-63, N794AL; Loss of Control and Crash; Swanton, Ohio"	1992
10 (1of 2)	26	National Transportation Safety Board (NTSB) "USAIR Flight 105; Boeing 737-200, N283AU; Kansas City; Missouri"	1989
10 (1of 2)	27	Uncontrolled Collision with Terrain American International Airways Flight 808; Guantanamo Bay, Cuba"	1993
10 (1of 2)	28	National Transportation Safety Board (NTSB) "Runway Collision of USAIR Flight 1493; Boeing 737; LA, California"	1991
10 (1of 2)	29	National Transportation Safety Board (NTSB) "Northwest Airline Flights 1482 and 299; Runway Incursion and Collision; Romulus, Michigan"	1990
10 (1of 2)	30	National Transportation Safety Board (NTSB) "Occupant Injury Chart and Seating Diagram"	1989
10 (1of 2)	31	National Transportation Safety Board (NTSB) "Evergreen International Airlines McDonnell Douglas, DC-9-33F; Saginaw, Texas"	1989
10 (1of 2)	32	National Transportation Safety Board (NTSB) "What is NTSB and how Does it Investigate Wrecks"	1993

10 (1of 2)	33	National Transportation Safety Board (NTSB) "Avianca, The Airline of Columbia, Boeing 707-321B, HK 2016 Fuel Exhaustion; Cover Neck, New York"	1990
10 (1of 2)	34	Transport Canada "Synopses of Aircraft Accident; Civil Aircraft in Canada; Issue 2"	1977
10 (1of 2)	35	National Transportation Safety Board (NTSB) "Preliminary Report Aviation"	1989
10 (1of 2)	36	National Transportation Safety Board (NTSB) "In-Flight Engine Separation Japan Airline; Flight, 46E; Boeing 747-121, N473EV; Anchorage, Alaska"	1993
10 (1of 2)	37	National Transportation Safety Board (NTSB) " National Transportation Safety Board (NTSB) "Avianca, The Airline of Columbia, Boeing 707-321B, HK 2016 Fuel Exhaustion; Cover Neck, New York"	1990
10 (1of 2)	38	National Transportation Safety Board (NTSB) "Midair Collision, Mitsubishi Mu-2B-60, N74FB, and Piper P A-32-301, N82419; Greenwood, Indiana"	1992
10 (1of 2)	39	National Transportation Safety Board (NTSB) "Aloha Islanair, Flight 1712; Halawa Point, Hawaii"	1989
10 (2 of 2)	1	NTSB/AAR-91/09. DC-9-15. Loss of Control. Cleveland.	1991
10 (2 of 2)	2	NTSB-AAE-93/02. US Air Fokker F-28. LaGuardia, NY. To Stall/Icing.	1992
10 (2 of 2)	3	NTSB/AAR-91/02. Markair 737. Crash Unalakleet, Alaska.	1990
10 (2 of 2)	4	NTSB/SS/-85/09. Safety Study. Passenger Education.	1985
10 (2 of 2)	5	NTSB AAR-92/01/Summary. Beechjet Rome, GA.	1991
10 (2 of 2)	6	NTSB/AAR-88/10. Fairchild Metro III SA 227 AG NC.	1988
10 (2 of 2)	7	NTSB/AAR-92/06. United 737-291. Uncontrolled Collision. Colorado Springs.	1992
10 (2 of 2)	8	NTSB/AAR-92/04. Britt Emb-120RT. Structural Breakup, Eagle Lake, TX.	1992
10 (2 of 2)	9	NTSB/AAR-93/01. Beech I185 Collision. Mt. Haleakala, Maui.	1993
10 (2 of 2)	10	NTSB/AAR-93/08. Mitsubishi MU-2Br60. Zwingle, Iowa. (Loss of Propeller Blade/Crash)	1993
10 (2 of 2)	11	NTSB/AAR-94/01/Summary. GP Express Beech C-99. Shelton, Nebraska.	1994
10 (2 of 2)	12	NTSB/AAR-94/01. American DC-10-30. Dallas/Ft Worth	1993
10 (2 of 2)	13	NTSB/AAR-93/07. MD-11. Shemy, Alaska. China E. Airlines (inadvertent Slat Deployment).	1993
10 (2 of 2)	14	NTSB/AAR-94/02. China Airlines. MD-11-P/Japan.	1992

10 (2 of 2)	15	NTSB/AAR 94/02/Summary. Continental Express. Embraer EMB-120RT. Pine Bluff, Arkansas. (Loss Control-Overrun).	1993
10 (2 of 2)	16	NTSB/AAR-94/01. AA DC-10. Dallas Overrun.	1993
10 (2 of 2)	17	NTSB/AAR-89/03/Summary. South Central Airways. Piper PA-31. Kenai, Alaska 6F2S.	1989
10 (2 of 2)	18	UK Accidents.	1974
10 (2 of 2)	19	UK Accidents.	1975
10 (2 of 2)	20	UK Accidents.	1976
10 (2 of 2)	21	UK Accidents.	1977
10 (2 of 2)	22	UK Accidents.	1973
10 (2 of 2)	23	UK Accidents.	1979
10 (2 of 2)	24	UK Accidents.	1978
10 (2 of 2)	25	NTSB/AAR-92/05. Douglas DC-8-63. LOC Crash. Swanton, Ohio.	1992
10 (2 of 2)	26	NTSB/AAR-90/04. US Air 737 KC.	1989
10 (2 of 2)	27	NTSB/AAR-94/04. DC8 Crash Cuba.	1993
10 (2 of 2)	28	NTSB AAR-91/08. Runway Collision. USAIR 737 and Skywest Fairchild LAX.	1991
10 (2 of 2)	29	NTSB/AAR-91/05. NW 11482 and 299 Collision Runway Detroit.	1990
10 (2 of 2)	30	NTSB Docket. SA 437. United DC-10. Sioux City. Occupant Injury Seating Chart.	1989
10 (2 of 2)	31	NTSB/AAR-90/02. Evergreen DC-9. Saginaw, TX.	1989
10 (2 of 2)	32	NTSB Organization and How It Works.	1993
10 (2 of 2)	33	NTSB/AAR-91/04. Avianca 708. Fuel Exhaust. NY.	1990
10 (2 of 2)	34	Transport Canada. Civil Aircraft Accidents #2.	1977
10 (2 of 2)	35	NTSB Preliminary. 727. Tegucigalpa Crash.	1989
10 (2 of 2)	36	NTSB/AAR-93/06. Japan Airlines 747 Anchorage.	1993
10 (2 of 2)	37	NTSB/AAR-91/04. Avianca 707. Fuel Exhaust. NY.	1990
10 (2 of 2)	38	NTSB/AAR-93/05. Midair Collision MU-2B/Piper PA-32. Greenwood, Indiana.	1992
10 (2 of 2)	39	NTSB/AAR-90/05. Aloha Twin Otter. Molokai, Hawaii.	1989